

PRESSURE/TORQUE CONVERSION CHART

17MD

Pressure in PSI	Pressure in BAR	FT. LBS.	Nm
1000	69	1653	2241
1200	83	2012	2728
1400	97	2368	3211
1600	110	2772	3758
1800	124	3147	4267
2000	138	3471	4706
2200	152	3917	5311
2400	165	4286	5811
2600	179	4658	6315
2800	193	5028	6817
3000	207	5398	7319
3200	221	5770	7823
3400	234	6139	8323
3600	248	6512	8829
3800	262	6886	9336
4000	276	7257	9839
4200	290	7629	10344
4400	303	7977	10815
4600	317	8339	11306
4800	331	8698	11793
5000	345	9118	12362
5200	359	9416	12766
5400	372	9791	13275
5600	386	10161	13776
5800	400	10536	14285
6000	414	10912	14795
6200	427	11287	15303
6400	441	11677	15832
6600	455	12047	16334
6800	469	12435	16860
7000	483	12823	17386
7200	496	13200	17897
7400	510	13571	18400
7600	524	13919	18872
7800	538	14300	19388
8000	552	14717	19954
8200	565	15042	20394
8400	579	15433	20924
8600	593	15833	21467
8800	607	16191	21952
9000	621	16545	22432
9200	634	16935	22961
9400	648	17321	23484
9600	662	17696	23993
9800	676	18060	24486
10000	689	18446	25009

MAXDRIVE™ SERIES
 SQUARE DRIVE TORQUE WRENCHES