

PRESSURE/TORQUE CONVERSION CHART

**25MD**

Pressure in PSI	Pressure in BAR	FT. LBS.	Nm
1000	69	2450	3322
1200	83	2940	3986
1400	97	3430	4650
1600	110	3920	5315
1800	124	4410	5979
2000	138	4900	6644
2200	152	5390	7308
2400	165	5880	7972
2600	179	6370	8637
2800	193	6860	9301
3000	207	7350	9965
3200	221	7840	10630
3400	234	8330	11294
3600	248	8820	11958
3800	262	9310	12623
4000	276	9800	13287
4200	290	10290	13951
4400	303	10780	14616
4600	317	11270	15280
4800	331	11760	15944
5000	345	12250	16609
5200	359	12740	17273
5400	372	13230	17937
5600	386	13720	18602
5800	400	14210	19266
6000	414	14700	19931
6200	427	15190	20595
6400	441	15680	21259
6600	455	16170	21924
6800	469	16660	22588
7000	483	17150	23252
7200	496	17640	23917
7400	510	18130	24581
7600	524	18620	25245
7800	538	19110	25910
8000	552	19600	26574
8200	565	20090	27238
8400	579	20580	27903
8600	593	21070	28567
8800	607	21560	29231
9000	621	22050	29896
9200	634	22540	30560
9400	648	23030	31224
9600	662	23520	31889
9800	676	24010	32553
10000	689	24500	33218

MAXDRIVE™ SERIES  
SQUARE DRIVE TORQUE WRENCHES